

Takata airbag inflator may rupture resulting in serious injury or death.



Check the VIN for Outstanding Takata Airbag Inflator Recalls at:
www.honda.ca/recalls

Summary of Affected Honda Models

Effective as of April 2017

YEAR	MODEL NAME	FRONT VIEW	REAR VIEW	YEAR	MODEL NAME	FRONT VIEW	REAR VIEW
2001-2002*	Civic			2002*	Odyssey		
2001-2002*	Accord			2002*	CR-V		
* = Highest Risk Vehicles							
2003-2005	Civic			2003 - 2004	Odyssey		
2006-2008	Civic			2003 - 2006	CR-V		
2003	Accord Coupe 4-cylinder			2007 - 2011	CR-V		
2003-2007	Accord Sedan 4-cylinder			2003-2010	Element		
2008	Accord			2003-2008	Pilot		
2007-2008	Fit			2006-2014	Ridgeline		
2009-2014	Fit			2011-2015	CR-Z		
2010-2012	Insight						



Check the VIN for Outstanding Takata Airbag Inflator Recalls at:
www.acura.ca/recalls

Summary of Affected Acura Models

Effective as of April 2017

YEAR	MODEL NAME	FRONT VIEW	REAR VIEW	YEAR	MODEL NAME	FRONT VIEW	REAR VIEW
2001-2003*	EL			2003-2006	MDX		
2002-2003*	TL			2007-2012	RDX		
* = Highest Risk Vehicles							
2003	CL			2013-2015	RDX		
2004-2005	EL			2010-2013	ZDX		
2006-2008	CSX			2005-2012	RL		
2009-2014	TL			2013-2016	ILX		

Takata airbag inflator may rupture resulting in serious injury or death.

Le dispositif de gonflage de coussin gonflable Takata pourrait éclater, causant des blessures graves ou entraînant la mort.



Vérifiez le NIV pour les rappels non effectués des dispositifs de gonflage des coussins gonflables Takata, au :

www.honda.ca/recallsfre

Sommaire des modèles Honda concernés

En date d'avril 2017

ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE	ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE
2001-2002*	Civic			2002*	Odyssey		
2001-2002*	Accord			2002*	CR-V		
* = Véhicules les plus à risque							
2003-2005	Civic			2003 - 2004	Odyssey		
2006-2008	Civic			2003 - 2006	CR-V		
2003	Coupe Accord 4 cylindres			2007 - 2011	CR-V		
2003-2007	Berline Accord 4 cylindres			2003-2010	Element		
2008	Accord			2003-2008	Pilot		
2007-2008	Fit			2006-2014	Ridgeline		
2009-2014	Fit			2011-2015	CR-Z		
2010-2012	Insight						



Vérifiez le NIV pour les rappels non effectués des dispositifs de gonflage des coussins gonflables Takata, au :

www.acura.ca/recallsfre

Sommaire des modèles Acura concernés

En date d'avril 2017

ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE	ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE
2001-2003*	EL			2003-2006	MDX		
2002-2003*	TL			2007-2012	RDX		
* = Véhicules les plus à risque							
2003	CL			2013-2015	RDX		
2004-2005	EL			2010-2013	ZDX		
2006-2008	CSX			2005-2012	RL		
2009-2014	TL			2013-2016	ILX		

Le dispositif de gonflage de coussin gonflable Takata pourrait éclater, causant des blessures graves ou entraînant la mort.