

Upon deployment Takata airbag inflator may explode resulting in serious injury or death



NOTICE: AIRBAG SAFETY RECALL

Check the VIN for Outstanding Takata Airbag Inflator Recalls at:
www.honda.ca/recalls

Summary of Affected Honda Models

Effective as of September 2018

YEAR	MODEL NAME	FRONT VIEW	REAR VIEW	YEAR	MODEL NAME	FRONT VIEW	REAR VIEW
2001-2002*	Civic			2002*	Odyssey		
2001-2002*	Accord			2002*	CR-V		
* = Highest Risk Vehicles							
2003-2005	Civic			2003 - 2004	Odyssey		
2006-2011	Civic			2003 - 2006	CR-V		
2003-2007 2003	Accord sedan 4-cyl Accord coupe 4-cyl			2007 - 2011	CR-V		
2010-2014	Crosstour			2003-2010	Element		
2008-2012	Accord			2003-2008	Pilot		
2007-2008	Fit			2009-2015	Pilot		
2009-2014	Fit			2006-2014	Ridgeline		
2010,2012	Insight			2011-2015	CR-Z		



NOTICE: AIRBAG SAFETY RECALL

Check the VIN for Outstanding Takata Airbag Inflator Recalls at:
www.acura.ca/recalls

Summary of Affected Acura Models

Effective as of September 2018

YEAR	MODEL NAME	FRONT VIEW	REAR VIEW	YEAR	MODEL NAME	FRONT VIEW	REAR VIEW
2001-2003*	EL			2003-2006	MDX		
2002-2003*	TL			2007-2012	RDX		
* = Highest Risk Vehicles							
2003	CL			2013-2015	RDX		
2004-2005	EL			2010-2013	ZDX		
2006-2011	CSX			2005-2012	RL		
2009-2014	TL			2013-2016	ILX		
2009-2013	TSX						

Upon deployment Takata airbag inflator may explode resulting in serious injury or death

Le dispositif de gonflage de coussin gonflable Takata pourrait éclater lors du déploiement, causant des blessures graves ou entraînant la mort.



Vérifiez le NIV pour les rappels non effectués des dispositifs de gonflage des coussins gonflables Takata, au :
www.honda.ca/recallsfre

Sommaire des modèles Honda concernés

En date de septembre 2018

ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE	ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE
2001-2002*	Civic			2002*	Odyssey		
2001-2002*	Accord			2002*	CR-V		
* = Véhicules les plus à risque							
2003-2005	Civic			2003 - 2004	Odyssey		
2006-2011	Civic			2003 - 2006	CR-V		
2003-2007 2003	Berline Accord 4 cyl. Coupe Accord 4 cyl.			2007 - 2011	CR-V		
2010-2014	Crosstour			2003-2010	Element		
2008-2012	Accord			2003-2008	Pilot		
2007-2008	Fit			2009-2015	Pilot		
2009-2014	Fit			2006-2014	Ridgeline		
2010, 2012	Insight			2011-2015	CR-Z		



Vérifiez le NIV pour les rappels non effectués des dispositifs de gonflage des coussins gonflables Takata, au :
www.acura.ca/recallsfre

Sommaire des modèles Acura concernés

En date de septembre 2018

ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE	ANNÉE	MODÈLE	VUE AVANT	VUE ARRIÈRE
2001-2003*	EL			2003-2006	MDX		
2002-2003*	TL			2007-2012	RDX		
* = Véhicules les plus à risque							
2003	CL			2013-2015	RDX		
2004-2005	EL			2010-2013	ZDX		
2006-2011	CSX			2005-2012	RL		
2009-2014	TL			2013-2016	ILX		
2009-2013	TSX						

Le dispositif de gonflage de coussin gonflable Takata pourrait éclater lors du déploiement, causant des blessures graves ou entraînant la mort.